

# COLD WORK TOOL STEEL

Stan- dards	1.2379	(DIN)	Properties			
	X153CrMoV12	(EN)	Dimensionally stable, ledeburitic 12% chromium steel with very good wear resistance and acceptable toughness.			
	D2	(AISI)				
	~ SKD11	(JIS)	Application  High-performance cutting tools (dies and punches), die-cutting tools, woodworking tools,			
Delivery condition	annealed		shear knives for thin items, thread rolling tools. Drawing, deep drawing and extrusion press tools, pressing tools for the ceramic and pharmaceutical industry, cold rolling (work rolls) for multi-roll stands, gauges, smaller plastic molds, which require high wear resistance.			

#### Chemical Composition (%)

С	Si	Mn	Cr	Мо	V
1.55	0.30	0.30	11.30	0.75	0.75

#### **Material Characteristics**

	Wear resistance abrasive	Wear resistance adhesive	Toughness	Compressive strength	Dimensional stability during heat treatment
BÖHLER K110	***	*	*	**	**
BÖHLER K100	***	*	*	*	**
BÖHLER K340	***	***	***	***	***
BÖHLER K353	**	***	****	**	**
BÖHLER K360	***	***	**	***	***
BÖHLER K390	****	****	***	***	***
BÖHLER K490 MICROCLEAN	***	***	****	***	***
BÖHLER K890	***	***	****	***	***

<sup>\*)</sup> The evaluation of the characteristics refers **only** to the brands considered here.

### Heat treatment

Annealing				
Temperature	800 - 850°C 1472 - 1562°F	Controlled slow oven cooling with 10 to 20°C/h (50 to 68°F/h) up to ca. 600°C/1112°F, further cooling in air. Supplied hardness max.: 250 HB		
Stress relieving				
Temperature	Slow oven cooling. For stress relief after extensive machining or at complicated tools. Holding time after complete through heating 1 - 2 hours in neutral atmosphere.			
Hardening				
Temperature	1030 - 1070°C 1886 - 1958°F	Difficultly shaped tools in air, simply shaped tools in compressed air, oil, hot bath (220 to 250°C/428 to 482°F or 500 to 550°C/932 to 1022°F) or gas. Holding time after complete soaking: 15 to 30 minutes. Achievable hardness: 58 - 61 HRC.		




Cross-comparisons with other reviews are discouraged due to different framework conditions.






#### Continuous cooling CCT curves



Austenitising temperature: 1080°C/1976°F
Holding time: 30 minutes
O Hardness in HV
2 ... 100 phase percentages
0,40 ... 59,8 cooling parameters, i. e.
Cooling from 800 - 500°C (1472 - 932°F) in s x 10<sup>-2</sup>
2 ... 1 K/min cooling rate in
K/min in the 800 - 500°C (1472 - 932°F) range
Range of grain boundary martensite formation
KgM ... Grain boundary martensite

#### Tempering chart



#### **Tempering**

Slow heating to tempering temperature immediately after hardening/time in furnace 1 hour for each 20 mm of workpiece thickness but at least 2 hours/cooling in air.

Please refer to the tempering chart for obtainable hardness after tempering.

Tempering after the secondary hardness maximum is recommended.

## Hardening temperature 1030°C / 1886°F 1070°C / 1958°F

#### Physical properties at 20°C/68°F

Density	7.67	[kg/dm³]
Thermal conductivity	23.90	[W/(m.K)]
Specific heat	470	[J/(kg.K)]
spec. electrical resistance	0.65	[Ohm.mm <sup>2</sup> /m]
Modulus of elasticity	200	[GPa]

Temperature [°C/°F]	100/212	200/392	300/572	400/752	500/932	600/1112	700/1292
Thermal expansion [10 <sup>-6</sup> m/(m.K)]	11.0	11.4	11.9	12.2	12.7	12.8	12.1

For more information visit www.voestalpine.com/bohler-edelstahl

#### voestalpine BÖHLER Edelstahl GmbH & Co KG

Mariazeller Straße 25 8605 Kapfenberg, Austria T. +43/50304/20-6066 E. info@bohler-edelstahl.at www.voestalpine.com/bohler-edelstahl

